

Röhm GmbH • Deutsche-Telekom-Allee 9 • 64295 Darmstadt • Germany

18/03/2021

To whom it may concern

Bastian Salzsieder
Regulatory Affairs

Deutsche-Telekom-Allee 9
64295 Darmstadt
Germany

T +49 6151 863 7559
bastian.salzsieder@roehm.com

DEGADUR® 112, 165, 332, 420, 510, 526, 527 and 530
DEGADUR® Crack Sealer

Dear Sir or Madam,

Based on the composition information and the used raw-materials for the manufacturing process of the above-mentioned products we hereby confirm that none of the known substance in these products are listed in the excel file "LBC-Red-List-CASNR-Guide-2021.xlsx" (Jan. 2021). Please also refer to our SDS of the related products.

With best regards

Röhm GmbH
Product Stewardship


i.A. Petra Jentzsch


i.A. Bastian Salzsieder

Röhm GmbH
Deutsche-Telekom-Allee 9
64295 Darmstadt
Germany
www.roehm.com

Chairman of the Supervisory Board
Dr. Dahai Yu

Managing Directors
Dr. Michael Pack
Dr. Hans-Peter Hauck
Martin Krämer

Registered Office is Darmstadt
Register Court Darmstadt Local Court
Commercial Registry B 100475

Röhm GmbH • Deutsche-Telekom-Allee 9 • 64295 Darmstadt • Germany

30/04/2021

To whom it may concern

Bastian Salzsieder
Regulatory Affairs

Deutsche-Telekom-Allee 9
64295 Darmstadt
Germany

T +49 6151 863 7559
bastian.salzsieder@roehm.com

DEGADUR® 112, 165, 332, 420, 510, 526, 527 and 530
DEGADUR® Crack Sealer

Living Building Challenge (NZ Red list)

Dear Sir or Madam,

Referring to the **RL-004a Proprietary Ingredients** request regarding NewZealand Red list, we hereby confirm that the minimum of 50% (by weight) of the compounds in the above-mentioned products are disclosed on the related Safety data sheets.

With best regards

Röhm GmbH
Product Stewardship


i.A. Petra Jentzsch


i.A. Bastian Salzsieder

Röhm GmbH
Deutsche-Telekom-Allee 9
64295 Darmstadt
Germany
www.roehm.com

Chairman of the Supervisory Board
Dr. Dahai Yu

Managing Directors
Dr. Michael Pack
Dr. Hans-Peter Hauck
Martin Krämer

Registered Office is Darmstadt
Register Court Darmstadt Local Court
Commercial Registry B 100475